



V2+V2+V2+V2+V2+V2+ V- V- V- V- V- V-  
12VDC OUTPUT 2

V2+V2+V2+V2+V2+V2+ V- V- V- V- V- V-  
12VDC OUTPUT 1

PRT-PSU-DIN

POWER

V1 OUT

STATUS

V2 OUT

FAULT

BATTERY

TEMP



MAX

OUTPUT CURRENT

N+ N- NA NB  
12VDC IN RS485 NETWORK

B- B+  
BATTERY

NC C NC C TP  
AC FAIL BATT FAIL TAMPER

L N  
110~230VAC IN

